


The *Miracle* Stainless Steel Cover Track solution for window rail repairs

The new 220630 *Miracle* Stainless Steel Cover Tracks can be used over damaged window tracks to restore new life. An easy to fit and cost effective lifetime solution. Unlike aluminum, the *Miracle* track is so tough that normal drill bits will go blunt trying to drill into it.



Step 1. Measure and cut track to length then test fit. Clean track to be free from dirt, oils etc.

Time to do task - 2 minutes.


Step 2. Mix polyester filler product to fix tracks. Use less hardener for a slower setting time or if confident use more hardener for a fast setting time.

Time to do task - 1 minute.



Step 3. Using a flat blade, fill the *Miracle* Stainless Steel track with the mixed polyester product. Use the flat blade to remove excess from back of track.

Time to do task - 1 minute.



Step 4. Push cover track over existing track and press down to squeeze out resin filler. Do not worry about cleaning up any excess resin filler at this stage. Very important to have track seated before resin filler begins to gel.


Time to do task - 1 minute.

Step 5. Once resin filler has gel set, use a flat screwdriver blade to run along both sides to clean out excess filler product. This is a quick and clean process. Use a vacuum to suck out loose material and job is done.

Time to do task - 1 minute.

It takes about six minutes total to complete the job.

The new cover track once installed is there for life and is very hard to damage. All that is left is to replace the window sash and see just how well it now runs.



1300 44 03 09